LASER PEGS®
The Ultimate Toy For Kids®

9025
EXPERIENCE SERIES
MYTHOLOGY
For Boys And Girls
Ages 5 And Up

16 Models+
Any creation you can build

LIGHTED
CONSTRUCTION SET INCLUDES:
· 20 Laser Pegs®
· 80 Construction Parts
· Triangle Power Base
· Instruction Manual

Requires 3 AA Batteries

Batteries NOT Included

Please read manual before you begin! Failure to follow this manual's instructions may result in damage to the Triangle Power Base, AC adapter and/or Laser Pegs®. Not adhering to these directions will void the manufacturer's warranty. Packing has to be kept since it contains important information.

⚠ **WARNING:**
CHOKING HAZARD-Small parts. Not for children under 3 yrs. Do not submerge in water.

Construction Compatible
Compatible with other construction kits

EN71, RoHS COMPLIANT
This product complies to all safety requirements of ASTM F 963

MODEL INSTRUCTIONS

All additional model instructions can be downloaded at www.LaserPegs.com

Laser Pegs® Parts List
There is No LED In The 90 Degree Peg

- Y PEG x2
- 45° PEG x4
- 90° PEG x4
- SQUARE PEG x1
- SQUARE M-M PEG x1
- STRAIGHT T-PEG x2
- TRIDENT PEG x1
- TRUSS PEG x2
- STACKABLE x2
- WHEEL PEG x1

Color Code → Each Laser Peg® is color coded on the circuit board inside each shape. There is No LED In The 90 Degree Peg.

Laser Pegs® Stackable
Laser Pegs® link that allows you to connect to other construction kits.

Triangle Power Base

Laser Pegs® Peg Cord

Construction Parts List
x2, x2, x2, x2, x2, x2, x1, x2, x2, x1, x2, x4, x8, x2, x4, x8, x1, x2, x2, x2, x2, x2, x4, x4, x4, x4, x4, x2, x4, x4, x4

### www.LaserPegs.com

---

Connecting Pegs

To construct with Laser Pegs®, slide two pieces together to form a connection. Slide each piece on and off smoothly. To build away from the Triangle Power Base, use the peg cord in one of the top three peg holes to illuminate your model! The 90° pegs are essential to construction but they DO NOT ILLUMINATE.

Press button to turn on/off
Push button to cycle through 3 different light settings.

- **Power Button**
- **Peg Holes**
- **AC Adapter Connection**

Connect Laser Pegs® TRIANGLE POWER BASE

Connect cord to model.

To build away from the Laser Pegs® Triangle power base use the peg cord in one of the top three holes to illuminate your model!

When you remove a peg from another peg or model DO NOT PULL ON CORD!

When Using Batteries

1. Remove screws.
2. Place three AA batteries in the correct position - as displayed inside the Triangle Power Base.
3. Push RED button to turn on!
4. Do not mix old and new batteries.
5. Do not mix alkaline, standard (carbon-zinc), or rechargeable (nickel-cadmium) batteries!
6. Exhausted batteries are to be removed from the power base.
7. Never connect more than 200 Laser Pegs®
8. Non-rechargeable batteries are not to be recharged.
9. Rechargeable batteries are only to be charged under adult supervision.
10. Rechargeable batteries are to be removed from the toy before being charged.
11. Batteries are to be inserted with the correct polarity.
12. The supply terminals are not to be short-circuited.

Remove the three Philips head screws with a 4mm screw driver.
Requires (3AA) Batteries

Using an AC Adapter

Remove all batteries from Laser Pegs® power base before using the 5 volt AC adapter.

When using an AC Adapter, **NEVER** place the adapter plug into the Triangle Power Base top peg holes.

*To avoid short-circuits, keep metal objects and other un-authorized materials from obstructing the peg holes.

Never connect more than 200 Laser Pegs® when using a 5 volt (2000mA) AC Adapter.

The AC adapter used with the power base are to be regularly examined for damage to the cord, plug, enclosure and other parts, and in the event of such damage, they must not be used until the damage has been repaired.

WARNING! Each Laser Peg® draws current from the batteries. Therefore, the more pegs you use, the quicker you will deplete your battery power! As the power weakens, the current will slowly fail and some Laser Pegs® will illuminate (typically the reds and yellows) and some won't. When the Laser Pegs® dim the Laser Pegs® are not broken, they just need stronger batteries or an AC Adapter. You have 3 simple options...
1. Use a 5 volt AC Adapter –available from www.LaserPegs.com
2. Change the batteries.
3. Use high quality batteries. They will last a little longer, but they will still deplete rapidly the more laser pegs you connect!


FACTOID

APEP
Model
Difficulty Level
3

A

STEP **1**

STEP **2**

STEP **3**

STEP **4**

STEP **5**

STEP **6**

STEP **7**

STEP **8**

STEP **9**

STEP **10**

STEP **11**

STEP 12

STEP 13

STEP 14

STEP 15

STEP 16

B

STEP 17

STEP 18

STEP 19

STEP 20

STEP 21

STEP 22

STEP 23

STEP 24

STEP 25

STEP 26

C

STEP 27

STEP 28

STEP 29

STEP 30

STEP 31

STEP 32

STEP 33

STEP 34

STEP 35

STEP 36

D

STEP 38 COMBINE B

STEP 39 COMBINE C

STEP 40

COMBINE

A

ATTACH MODEL TO TRIANGLE POWER BASE