

LASER PEGS®

The Ultimate Toy For Kids®

9025
EXPERIENCE SERIES
MYTHOLOGY

For Boys And Girls
Ages 5 And Up

16 Models+
Any creation you can build

LIGHTED
CONSTRUCTION SET INCLUDES:

• 20 Laser Pegs®
• 80 Construction Parts
• Triangle Power Base
• Instruction Manual
Requires 3 AA Batteries

Batteries NOT
Included


EN71, RoHS COMPLIANT

This product complies to
all safety requirements
of ASTM F 963


Compatible with other construction kits

MODEL INSTRUCTIONS

All additional model instructions can
be downloaded at www.LaserPegs.com




Color Code Each Laser Peg® is color coded on the circuit board inside each shape. There is No LED In The 90 Degree Peg.



Laser Pegs® link that
allows you to connect to
other construction kits.

Triangle Power
Base


Laser Pegs®
Peg Cord



www.LaserPegs.com


This manual is copyright and cannot be reproduced or used online without Laser Pegs® Ventures LLC permission. Copyright 2013 © All Rights Reserved US Patent #7,731,558 Additional Global & Multiple Patents Pending. Laser Pegs® Ventures LLC. 8304 Consumer Ct., Sarasota FL 34240. Contact: Support@LaserPegs.com

Connecting Pegs




Press button to turn on/off

Push button to cycle
through 3 different
light settings.



Connect Laser Pegs® TRIANGLE POWER BASE




To build away from the Laser Pegs® Triangle Power Base use the peg cord in one of the top three holes to illuminate your model!

When you remove a peg from another peg or model DO NOT PULL ON CORD!

When Using Batteries


1. Remove screws.
2. Place three AA batteries in the correct position - as displayed inside the Triangle Power Base.
3. Push RED button to turn on!
4. Do not mix old and new batteries.
5. Do not mix alkaline, standard (carbon-zinc), or rechargeable (nickel-cadmium) batteries!
6. Exhausted batteries are to be removed from the power base.
7. Never connect more than 200 Laser Pegs®
8. Non-rechargeable batteries are not to be recharged.
9. Rechargeable batteries are only to be charged under adult supervision.
10. Rechargeable batteries are to be removed from the toy before being charged.
11. Batteries are to be inserted with the correct polarity.
12. The supply terminals are not to be short-circuited.



Requires (3AA) Batteries

Using an AC Adapter

Remove all batteries from Laser Pegs® power base before using the 5 volt AC adapter.



*To avoid short-circuits, keep metal objects and other un-authorized materials from obstructing the peg holes.

Never connect more than 200 Laser Pegs® when using a 5 volt (2000mA) AC Adapter.

The AC Adapter and the Power Base are to be regularly examined for damage to the cord, plug, enclosure and other parts, and in the event of such damage, they must not be used until the damage has been repaired.

WARNING! Each Laser Peg® draws current from the batteries. Therefore, the more pegs you use, the quicker you will deplete your battery power! As the power weakens, the current will slowly fail and some Laser Pegs® will illuminate (typically the reds and yellows) and some won't. When the Laser Pegs® dim the Laser Pegs® are not broken, they just need stronger batteries or an AC Adapter.

You have 3 simple options...

1. Use a 5 volt AC Adapter -available from www.LaserPegs.com
2. Change the batteries.
3. Use high quality batteries. They will last a little longer, but they will still deplete rapidly the more laser pegs you connect!



GORGON--The snaked-haired Medusa who will turn you to stone if you look at her.




GORGON WITH BOW

Model
Difficulty
Level


3





STEP
1




STEP
2




STEP
3





STEP
4




STEP
5




STEP
6




STEP
7




STEP
8




STEP
9








STEP
10




STEP
11




STEP
12




STEP
13





STEP
14




STEP
15




STEP
16




STEP
17




STEP
18




STEP
19
COMBINE
D




STEP
20
COMBINE
C




STEP
21
COMBINE
B



STEP
22
COMBINE
A




STEP
23
COMBINE
E



ATTACH MODEL TO THE TRIANGLE POWER BASE

STEP
24



www.LaserPegs.com

Copyright 2013© All Rights Reserved Global & Multiple Patents Pending.
US Patent #7,731,558